

HILLSBORO INLET DISTRICT
CAUTION

1. Hazardous inlet, local knowledge required.
2. Chart is not to scale or intended for navigation.
3. Pass at idle speed.
4. Current at bridge can run at six knots. Give way to vessel moving with current.
5. Ebb currents tend to push vessels onto the south reef.
6. Flood currents tend to push vessels off the south reef.
7. Moving sands reduce inlet depth.
8. Wave troughs have less water depth that when flat calm

JACK HOLLAND
CHAIRMAN
LAURENCE GORE
VICE-CHAIRMAN

COMMISSIONERS

DENISE BRYAN
RANDY STRAUSS
MO TARIFI
TYLER CHAPPELL
SCOTT T. LOESEL
HANK SARKIS